

CLIENT INFORMATION

Client: *****
Requested On: Sep 8, 2025
Phone: *****
Email: *****

Kitting, Logistics, and Support provided by: SimpleLab, Inc.

Questions? For fastest assistance:
hello@gosimplelab.com
Do not contact facility technicians directly.

TESTING PERFORMED

Testing Requested: BPA Water Test
Matrix: Drinking Water
Testing / Report ID: FV2YAG
Testing Facility: Eurofins Scientific
Facility Location: 110 S Hill St
South Bend, Indiana 46617

SAMPLE INFORMATION

Collection Date: Oct 28, 2025
Collected By: *****
Received Date: Oct 30, 2025
Reported On: Dec 1, 2025
Sample Location: Deer Park (Plastic)
Sample Address: *****

TESTING NOTES FROM SIMPLELAB

There were no problems with analytical events associated with this report unless noted. Quality control data is within laboratory defined or method specified acceptance limits except where noted. If you have any questions regarding these test results, please contact hello@gosimplelab.com

TEST RESULTS

ANALYTE	UNIT	RESULT	MDL	RL	METHOD
Bisphenol A	µg/L	NOT DETECTED	0.0074	0.02	Pharmaceuticals and Personal Care Products (LC/MS/MS) - Negative Ionization

How To Read Your SimpleLab PDF Report

MDL: The Method Detection Limit is the lowest concentration which the analysis team and instrumentation is configured to measure.

RL: The Method Reporting Limit is the lowest level at which the laboratory can confidently and accurately quantify the concentration.